


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?		
D1028-164	Dye	4/23/2009	ADS/TM	S13EE1012MH	Damp	NA		
Address	4024 Oswego Avenue		Location	Curb	Status	Public	Source	Catch Basin



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-164	Dye	4/23/2009	ADS/TM	S13EE1012MH	Damp	NA
Address 4024 Oswego Avenue			Location Curb	Status Public	Source Catch Basin	

Observations & Photos

